



Applies To: **2003–05 Accord L4** – All with A/T
2003–05 Element – All with A/T

August 8, 2006

Vehicle Moves (Creeps) Faster Than Expected When Idling in Gear (Supersedes 06–041, dated July 18, 2006, to update the information marked by the black bars)

SYMPTOM

The vehicle moves slightly faster than expected with the transmission in gear, foot off the brake, and foot off the throttle.

PROBABLE CAUSE

The PCM PGM-FI software causes extra engine torque after a cold start.

CORRECTIVE ACTION

Update the PCM PGM-FI software.

SOFTWARE INFORMATION

Accord: HDS software version 2.005.004 (or later)
 Element: HDS software version 2.005.008 (or later)

2003–04 Accord L4:

PGM-FI PROGRAM ID	PGM-FI PROGRAM P/N
AA3150 (or later)	37805-RAA-315 (or later)
AA3170 (or later)	37805-RAA-317 (or later)
AA3090 (or later)	37805-RAA-309 (or later)
AD4150 (or later)	37805-RAD-415 (or later)

2005 Accord L4:

PGM-FI PROGRAM ID	PGM-FI PROGRAM P/N
AD3050 (or later)	37805-RAD-305 (or later)
AD3070 (or later)	37805-RAD-307 (or later)
AD3090 (or later)	37805-RAD-309 (or later)

2003–04 Element:

PGM-FI PROGRAM ID	PGM-FI PROGRAM P/N
ZD3060 (or later)	37805-PZD-306 (or later)
ZD3070 (or later)	37805-PZD-307 (or later)

2005 Element:

PGM-FI PROGRAM ID	PGM-FI PROGRAM P/N
ZDA710 (or later)	37805-PZD-A71 (or later)
ZDA810 (or later)	37805-PZD-A81 (or later)

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

Operation Number: 125517
 Flat Rate Time: 0.3 hour
 Failed Part: P/N 37820-RAA-305
 H/C 8423972
 Defect Code: 03214
 Symptom Code: 09201
 Template ID: 06-041A
 Skill Level: Repair Technician

Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Parts and Service Manager or your Zone Office. You must request consideration, and get a decision, before starting work.

REPAIR PROCEDURE

Update the HDS software (refer to Service Bulletin 01–023, *Updating the ECM/PCM*):

Model	HDS Software Version
Accord	2.005.004 (or later)
Element	2.005.008 (or later)